


AXIS thermal body temperature measurement w/alarm zones.



AXIS cameras support up to six temperature alarm zones that can be used to trigger an alarm. It offers two kinds of alarms triggered by a deviation of the temperature: if the temperature goes beyond a set limit, or if it increases too rapidly. The spot temperature functionality is used to view the temperature of a particular area. Isothermal palettes highlight

temperature-spans in the image, making it easier to visualize hot spots to identify overheated equipment or areas.



- > Temperature alarm
- > Isothermal palettes
- > Spot temperature reading
- > High performance intelligent video
- > Efficient, visible and real-time

GWT Controls Inc. 1-403-879-2277 customerservice@gwtcontrols.com